

## CARELESSNESS CAUSES FIRE

This item complies with the requirements of  
the FURNITURE AND FURNISHINGS  
(FIRE) (SAFETY) REGULATIONS 1988.

This item does not have a schedule 3  
interliner.

All filling materials have been tested for  
compliance with the relevant ignitability  
requirements.

Covers and fillings are cigarette resistant.  
Covers are match resistant.

Further details from your retailer.

G8002 / AA-137895-1

泡沫 35 公斤 / 立方呎

## **CARELESSNESS CAUSES FIRE**

Batch/ID No OF:KV0051LV

To comply with The Furniture and  
Furnishings (Fire) (Safety) Regulations:  
This article does not include a Schedule  
3 interliner.

2021-03-10

All foams, fillings and composites have  
been tested to ensure compliance with  
the relevant ignitability test. All covers  
and fillings have been tested to ensure  
that they are cigarette resistant. All  
covers have been tested to ensure that  
they are match resistant.

This article contains CM Foam which  
passes the specified test. All upholstery  
is cigarette resistant.

**SPECIALIST UPHOLSTERY  
CLEAN ONLY**

### **CARELESSNESS CAUSES FIRE**

This item complies with the requirements of  
the **FURNITURE AND FURNISHINGS**  
**(FIRE) (SAFETY) REGULATIONS 1988.**

This item does not have a schedule 3  
interliner.

All filling materials have been tested for  
compliance with the relevant ignitability  
requirements.

Covers and fillings are cigarette resistant.  
Covers are match resistant.

Further details from your retailer.

GB 002 / AA-137895-1

CARELESSNESS CAUSES FIRE

BATCH/I.D.NO.....1911B

TO COMPLY WITH THE FURNITURE  
AND FURNISHINGS(FIRE)(SAFETY)  
REGULATIONS 1988:

THIS ITEM DOES NOT INCLUDE A  
SCHEDULE 3 INTERLINER, ALL  
FOAMS, FILLINGS & COMPOSITES  
HAVE BEEN TESTED BY OUR  
SUPPLIER(S) TO ENSURE  
COMPLIANCE WITH THE RELEVANT  
IGNITABILITY TEST. COVERS &  
FILLINGS ARE CIGARETTE  
RESISTANT. COVERS ARE MATCH  
RESISTANT.

FURTHER DETAILS ARE AVAILABLE  
FROM YOUR RETAILER

TIME  
4123

CARELESSNESS CAUSES FIRE

BATCH/I.D.NO. 19179

TO COMPLY WITH THE FURNITURE  
AND FURNISHINGS(FIRE)(SAFETY)  
REGULATIONS 1988:

THIS ITEM DOES NOT INCLUDE A  
SCHEDULE 3 INTERLINER, ALL  
FOAMS, FILLINGS & COMPOSITES  
HAVE BEEN TESTED BY OUR  
SUPPLIER(S) TO ENSURE  
COMPLIANCE WITH THE RELEVANT  
IGNITABILITY TEST. COVERS &  
FILLINGS ARE CIGARETTE  
RESISTANT. COVERS ARE MATCH  
RESISTANT.

FURTHER DETAILS ARE AVAILABLE  
FROM YOUR RETAILER

BATCH I.D.No.....

16477

**TO COMPLY WITH THE FURNITURE  
AND FURNISHINGS(FIRE)(SAFETY)  
REGULATIONS 1988:**

**THIS ITEM DOES NOT INCLUDE A  
SCHEDULE 3 INTERLINER, ALL  
FOAMS, FILLINGS & COMPOSITES  
HAVE BEEN TESTED BY OUR  
SUPPLIER(S) TO ENSURE  
COMPLIANCE WITH THE RELEVANT  
IGNITABILITY TEST. COVERS &  
FILLINGS ARE CIGARETTE  
RESISTANT. COVERS ARE MATCH  
RESISTANT.**

JAN 11  
3125  
CARELESSNESS CAUSES FIRE

BATCH/I.D.NO. 3194C

TO COMPLY WITH THE FURNITURE  
AND FURNISHINGS(FIRE)(SAFETY)  
REGULATIONS 1988:

THIS ITEM DOES NOT INCLUDE A  
SCHEDULE 3 INTERLINER, ALL  
FOAMS, FILLINGS & COMPOSITES  
HAVE BEEN TESTED BY OUR  
SUPPLIER(S) TO ENSURE  
COMPLIANCE WITH THE RELEVANT  
IGNITABILITY TEST. COVERS &  
FILLINGS ARE CIGARETTE  
RESISTANT. COVERS ARE MATCH  
RESISTANT.

FURTHER DETAILS ARE AVAILABLE  
FROM YOUR RETAILER