

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.

REGISTERED BUSINESS DETAILS

Reg No: 586 389
 Company: Centurion Plumbing Services
 Address: Unit 2A Industrial Estate
Great North Rd, Warrington
 Postcode: IV6 2UT
 Tel: 01463 741471

INSPECTOR/INSTALLATION ADDRESS

Name & Title: Neil Edwards
 Address: Highfield House
Mir of Ore
 Postcode: IV6 3XJ
 Tel: _____

LANDLORD (OR AGENT) NAME & ADDRESS (if applicable)

Name & Title: _____
 Address: _____
 Postcode: _____
 Tel: _____

Number of appliances tested: 1

APPLIANCE DETAILS				FLUE TESTS				INSPECTION DETAILS								
Location	Make and Model	Type	Flue Type OF/RS/FL	Operating pressure in heat input kWh or Btu/h	Safety device(s) correct operation Yes/No/NA	Spillage test Pass/Fail/NA	Smoke pellet flow test Pass/Fail/NA	Initial combustion analyser reading	Final combustion analyser reading	Satisfactory termination Yes/No/NA	Flue visual condition Pass/Fail/NA	Adequate ventilation Yes/No	Landlord's appliance inspected Yes/No/NA	Appliance Visual Check Yes/No	Appliance serviced Yes/No	Appliance Safe to Use Yes/No
1	KITURN	Flueless	FL	36.09	YES	NA	NA	NA	NA	NA	NA	YES	NA	YES	YES	YES
2																
3																
4																
5																

For appliances not owned by the landlord the recorded 'Appliance Safe to Use' response is based on a visual check for obvious defects only

Gas Installation Satisfactory Visual Inspection: Yes No

Pipework: Satisfactory Visual Inspection: Yes No

Emergency Control Accessible: Yes No

Satisfactory Gas Tightness Test: Yes No

Equipotential Bonding Satisfactory: Yes No

GIVE DETAILS OF ANY FAULTS

1																
2																
3																
4																
5																

RECTIFICATION WORK CARRIED OUT:

Approved Audible CO Alarms Fitted & Located Correctly: Yes No N/A _____

Are CO Alarms in Date: Yes No N/A _____

Testing of CO Alarms Satisfactory: Yes No N/A _____

Smoke/Heat Alarms Located & Fitted correctly: Yes No N/A _____

OTHER COMMENTS OR OBSERVATIONS

Supply Chain not installed BUT
 customer made aware of it,
 flexible hose condition OK.

NEXT GAS SAFETY CHECK DUE BEFORE:

28/04/24

ISSUED BY (GAS ENGINEER)

Print Name: L FLAHERTY
 Licence No: 5365181
 Signed: [Signature]
 Issue Date: 28/4/23

RECEIVED BY

(Deduce as applicable)
 Tenant/Agent/Landlord/Home Owner _____
 Print Name: _____

Received By: _____
 Signed: _____

No one present at time of visit